

Task Hazard Report

Task Hazard ID: Plant 001 Sample

Date Printed: 3/5/2007 3:01:55 PM

Task Hazard Details

Task Hazard ID: Plant 001 Sample

Task Hazard Notes: The listed PPE is required in all production areas. Additional PPE may be required in specific areas.
Sample

Entered By: CIRSMA Administrator

Date Created: 01/08/2007

Lockout, Tagout, Test, Procedures apply to this activity

Activity: Entry into all production areas Sample

General Areas of Potential Injury:

Head

Specific areas of the potential injury	Protection devices used
Eyes	Safety Glasses

Nature of Injuries for the Above Area of Potential Injury

Sensory damage

Cause of the potential injury

Propelled objects

General Areas of Potential Injury:

Legs

Specific areas of the potential injury	Protection devices used
Foot	Safety shoes

Nature of Injuries for the Above Area of Potential Injury

Skeletal damage

Cause of the potential injury

Falling material/objects

Task Hazard Report

Task Hazard ID: Plant 001 Sample

Date Printed: 3/5/2007 3:01:55 PM

References to Assessment's Hazard Zone

1	Assessment: RA 0001 Hazard Zone: 1.2 Isles around robot cell Activity: Casual exposure to personnel walking past the hazard zone	Version: 1
2	Assessment: RA 0001 Hazard Zone: 1.0 Robot cell setup Activity: Robot setup	Version: 1
3	Assessment: RA 0001 Hazard Zone: 1.1 Robot cell clean up Activity: Remove scrap material	Version: 1
4	Assessment: RA 0001 Hazard Zone: 1.2 Isles around robot cell Activity: Casual exposure to personnel walking past the hazard zone	Version: 2
5	Assessment: RA 0001 Hazard Zone: 1.1 Robot cell clean up Activity: Remove scrap material	Version: 2
6	Assessment: RA 0001 Hazard Zone: 1.0 Robot cell setup Activity: Robot setup	Version: 2