

Task Hazard Report

Task Hazard ID: Plant 002 Sample

Date Printed: 3/5/2007 3:01:39 PM

Task Hazard Details

Task Hazard ID: Plant 002 Sample

Task Hazard Notes: The listed PPE is required in all production areas. Additional PPE may be required in specific areas.
Sample

Entered By: CIRSMA Administrator

Date Created: 01/08/2007

Lockout, Tagout, Test, Procedures apply to this activity

Activity: Entry into stamping press department Sample

General Areas of Potential Injury:

Head

Specific areas of the potential injury	Protection devices used
Ears	Ear plugs

Nature of Injuries for the Above Area of Potential Injury

Sensory damage

Cause of the potential injury

Noise levels > 85 dba