

Task Hazard Report

Task Hazard ID: Plant 003

Date Printed: 3/5/2007 3:02:20 PM

Task Hazard Details

Task Hazard ID: Plant 003

Task Hazard Notes: The listed PPE is required in all production areas. Additional PPE may be required in specific areas.
Sample

Entered By: CIRSMA Administrator

Date Created: 01/13/2007

Lockout, Tagout, Test, Procedures apply to this activity

Activity: Work in stamping press department Sample

General Areas of Potential Injury:

Arms

Specific areas of the potential injury	Protection devices used
Forearm	Kevlar cuffs
Hand	Kevlar gloves
Wrist	Kevlar sleeves

Nature of Injuries for the Above Area of Potential Injury

Skin damage

Cause of the potential injury

Sharp edges on equipment
Sharp edges on sheet metal